

Home Energy Assessment



Home

Jennifer Behrens 7101 Harvest Hill Rd Madison WI, 53517 (608) 836-0481 jbehrenswi@gmail.com

Assessment Date

Invalid date Invalid date

Assessment By

Emily Millar

President BPI analyst (608) 444-7584 emily@ steadystatesolution.com 9-3 M-F

Steady State Building Performance, LLC

8875 county RD ID Blue Mounds WI, 53517 Office: 608-444-7584 9-3 M-F

Proud to Partner with Focus on Energy



Powered by Snugg Pro # 100640



Buying your home was one of the largest investments you have made.

Now you can enhance your home's performance by making improvements that are smart for you, your family and the environment.


- Air sealing- attic perimeter, kitchen soffit, attic/basement stair juncture, fireplace/attic connectivity.
- Attic Insulation- Remove existing fiberglass and insulate to R60
- Sill box insulation- exposed joists- 2.5 inces of closed cell foam
- Caulk basement casement window
- Improve garage door weatherstripping

Inside Your Report Cover HES Concerns Solutions Upgrade Details Health & Safety Additional Notes Rebates & Incentives Metrics Tech specs Glossary



Home Energy Score

| ADDRESS: | 7101 Harvest Hill Rd |
|------------------|----------------------|
| | Madison, WI 53517 |
| HOME SIZE: | 1,212 square feet |
| YEAR BUILT: | 1980 |
| AIR CONDITIONED: | Yes |



Learn more at homeenergyscore.gov



The **Home Energy Score** is a national rating system developed by the U.S. Department of Energy. The **Score** reflects the energy efficiency of a home based on the home's structure and heating, cooling, and hot water systems.

OFFICIAL ASSESSMENT | Assessor ID WI-FOE-0064 | Assessed on Mar 22, 2018 | Label ID# 197919 | v2017